


Loading and Unloading Data from CoCo









1. First Connect your CoCo device by ethernet to your PC.

2. In VDS, click **Data Collector** > in the **Devices** menu, click **Load** > Click **CoCo**

https://help.go-ci.com/ Printed on 2025/11/07 22:37

device > Select the Device you are using > Click Next > Click Load Factories and Routes > Click Next

3. Your VDS will have Factories and Routes to choose to upload to your CoCo device. **Select options to upload >** Click **Upload >** Click **Finish**

From:

https://help.go-ci.com/ - Crystal Instruments Help

Permanent link:

https://help.go-ci.com/vds:transfer?rev=1734725264

Last update: 2024/12/20 20:07