




# Loading and Unloading Data from CoCo



Vibration Diagnostic System Synchronization Wizard | Database: smart


 **Select an option**

What do you want to do?

- Load Factories and Routes
- Sync Note Codes
- Delete Data

< Back    Next >    Cancel

Vibration Diagnostic System Synchronization Wizard | Database: smart

 **Upload factory and route to CoCo device or file folder**

Database/CoCo	Status
<input checked="" type="checkbox"/> WATER SERVICE	
<input checked="" type="checkbox"/> Conference Room	Only in Database.
<input checked="" type="checkbox"/> Factory	Only in Database.
<input checked="" type="checkbox"/> Test	Only in Database.
<input checked="" type="checkbox"/> test1	Only in Database.

Select.All    Deselect.All    Inverse Selection     Synchronize Factories

**Select which Factories and Routes to upload using the check boxes.  
Routes already on the CoCo will be updated.  
Routes and data may only be deleted manually from the CoCo.**

Upload

< Back    Finish    Cancel

1. First Connect your CoCo device by ethernet to your PC.
2. In VDS, click **Data Collector** > in the **Devices** menu, click **Load** > Click **CoCo**

**device > Select the Device you are using > Click Next > Click Load Factories and Routes > Click Next**

3. Your VDS will have Factories and Routes to choose to upload to your CoCo device.

**Select options to upload > Click Upload > Click Finish**

From:

<https://help.go-ci.com/> - **Crystal Instruments Help**

Permanent link:

<https://help.go-ci.com/vds:transfer?rev=1734725264>

Last update: **2024/12/20 20:07**